

**Notice of Proposed No Further Action Related To
A Petroleum Hydrocarbon Discharge**

**Steve's Service Station
315 South State Street
Ukiah, CA
Case No. 1TMC339**

**Internet Posting Date: 3/13/09
Target End of Comment Period: 4/13/09**

Problem Description:

On October 8, 1996, three underground gasoline storage tanks were removed from the property at 315 South state Street in Ukiah, California. Soil sampling indicated that there was a release of petroleum hydrocarbons to the subsurface from the tanks.

Environmental Investigation:

The environmental investigation included soil sampling from thirty (30) boring locations and installation of three groundwater monitoring wells. In January 2004, approximately 2,076 tons of impacted soil was removed from the site. Impacted soil was excavated to the extent possible laterally and to a depth of 14 feet below ground surface. Residual impacted soil is limited and does not extend to the first encountered shallow aquifer. Groundwater monitoring has been conducted from the three shallow monitoring wells since they were installed in 1998. Groundwater impacts at this site are defined and were never extensive. There were no detections of any petroleum hydrocarbons or associated chemicals of concern in the shallow aquifer during the last sampling conducted on October 8, 2008.

Proposed No Further Action

Regional Water Board staff plan to concur with no further action related to the release of petroleum products at 315 South State Street Ukiah, CA. This investigation will be closed at the end of the comment period identified above without further notice to the public, unless new and significant information is submitted indicating that further remedial actions should be required. Records for the site are contained in a file identified as Steve's Service Station and are available for review by calling (707) 576-2220. You may also contact Beth Lamb at (707) 576-2669 or blamb@waterboards.ca.gov with any questions.